Engine:		Interior:	
Fuel Injectors (all 6)	\$100	Floor Mats	\$100
Master cylinder/booster	\$50	Carpet (floor)	\$100
Horns	\$10	Carpet (side console)	\$50
ABS	, \$50	Wood Trim (complete)	\$100
Intake Manifold	\$40	Front Seats (2)	\$200
Coils (6)	\$50	Rear Seats (complete)	\$150
Coolant Reservoir	\$25	Spare	\$50
Hood Latch	\$20	Headliner (complete)	\$400
Washer Fluid Reservoir	\$25	Sunroof	\$100
Water Pump	\$30	Steering Wheel Airbag	\$50
Starter	\$25	Air bag (passenger)	\$50
TOTAL	\$425	Side Airbags (2)	\$75
33.7.3	y	Airbag Module	\$25
		Blower Motor	\$25
PODV.		Gauge Cluster (complete) \$50	
BODY:		Weather Stripping (4)	\$100
Fuel Door	\$50	Radio	\$50
Tail Lights (both)	,\$50	Parking Sensor Module	\$25
Hood (complete)	\$300	<mark>Total</mark>	\$1,700
Fenders (both)	\$100		
Trunk	\$100		
Door (complete-front)	\$200		
Door (complete-front)	\$200	Parts: \$4,47	<mark>'5</mark>
Door (complete-rear)	\$200	-	
Door (complete-rear)	\$200	+ Scrap Frame: \$190	
Driver Side Skirt	\$150		
Side Skirt (passenger)	\$50	Total: \$4,66!	5
Headlights (restored)	\$300	+ 1 / 000	
Wheels	\$250	- Car Cost: \$1,484	4
Rear Bumper	\$150	34. 55511 42) 10	<u>•</u>
Rear Crash Bar	\$50	TOTAL Profit: \$3,181	
<u>TOTAL</u>	<mark>\$2,350</mark>	TOTAL PROTE: 5	$\mathbf{D}'\mathbf{TQT}$